




PDS Vehicle Inspections Inspection Report



Customer	John Smith
Bank/Finance Company	
Date Inspected	23/9/2017
Make / Model	Holden VE Commodore
Build Date/Compliance Date	10/08/09
Registration Number	ABC123
Registration Expiry	12/01/2018
Odometer Showing	86604
Chassis / VIN Number	ABC12345789
Engine Number	ABC12345587
Inspection Type	Finance

Car Inspected





The vehicle appears in tidy overall condition from the visual appearance.

The Compliance Plates, Chassis/VIN number, Odometer reading have been sighted and recorded by the PDS Vehicle Inspector at the time of the inspection.

Note: Engine numbers may not visible due to location not being accessible.

Engine numbers may be taken from registration papers for the report or recorded from the VIN Plate or Label if not visible as some engine numbers can be in locations difficult to see.

This finance inspection report is for the purpose to validate the inspected vehicle along with any compliance plates attached or VIN/Chassis number stamped in the vehicle and the odometer reading showing at the time of the inspection.

The inspection does not examine or report on the mechanical condition of the vehicle or any other repairs to the body or paint of the vehicle.

It may be noted if a vehicle has exterior body damage or significant problem that would relate to the potential value of the vehicle that would be in the interest of a lender knowing.

Inspector name

Date:

Inspector Signature

Disclaimer

Please note: our inspection is based on a physical description of what can be visually seen at the time of the vehicle inspection.

We do not guarantee the authenticity of the vehicle presented.

VIN numbers, Chassis Numbers or Engine Numbers and Odometer readings are recorded at time of inspection.

Vehicle Information is taken from the vehicle being presented for inspection.

Customers should contact [PDS Vehicle Inspections](#) if they do not understand any part of the report and or require further information.